Block

Flowchart

In recent versions of prominent CAD programs, there is no command line option. Instead there is a dialog box with several settings.

Dialog box parameters

Label	Look	Type
Name	Textbox+Dropdown List	String

From:
https://dokuwiki.librecad.org/ - **Wiki**

Permanent link:
https://dokuwiki.librecad.org/doku.php/dev:generic:toolcharts:block?rev=1591728284

Last update: **2020/06/09 18:44**