# Block

### Flowchart

In recent versions of prominent CAD programs, there is no command line option. Instead there is a dialog box with several settings.

Dialog box parameters

| Label | Appearance | Type |
|---|---|---|
| Name | Text-box+Drop-down List | String |
| Description | Multi-line Text-box | String |
| Annotative Scaling | Checkbox | Bool |
| Apply uniform scale | Checkbox | Bool |
| Allow block to explode | Checkbox | Bool |
| Units | Drop-down List | string |
| Select in graphic area | Button | |
| X | Text-Box | Decimal |
| Y | Text-Box | Decimal |
| Y | Text-Box | Decimal |

From:
https://dokuwiki.librecad.org/ - **Wiki**

Permanent link:
**https://dokuwiki.librecad.org/doku.php/dev:generic:toolcharts:block?rev=1591728830**

Last update: **2020/06/09 18:53**